

**FASTER WORK ORDER PRINT**

**WORK ORDER # 69880  
EQUIPMENT # 9604**

Date In: 10/02/2015 Date Out: 10/05/2015 Work Order Status: C Work Order Shop: W05

|                |                             |                          |                  |
|----------------|-----------------------------|--------------------------|------------------|
| COLOR: White   | COMPANY: 001                | TIRE SIZE 1: LT225X75R16 | FUEL TYPE 1: U   |
| YEAR: 2006     | DEPT: Trans/Agin            | TIRE SIZE 2: LT225X75R16 | FUEL T YPE 2:    |
| MAKE: FORD     | CLASS: 175                  | ENGINE SIZE: 6.8L        | FUEL TYPE 3:     |
| MODEL: E-350   | SITE: 175                   | TRANS: 5SPD AUTO         | EQ AVAIL CODE: 1 |
| LICENSE: 57893 | SERIAL #: 1FDWE35S96DA32014 | TITLE:                   | BILLING CODE: 1  |
| OPERATOR:      | MONITOR GROUP:              | CURRENT METERS:          | M 193,912        |

**TECHNICIAN REPAIRS PERFORMED**

| TECH ID | HOURS | OVER TIME | SHIFT | LABOR END DATE | REPAIR TYPE  | RTY DESCRIPTION                         | LABOR COST |
|---------|-------|-----------|-------|----------------|--------------|---|------------|
| 936     | 1.04  | N         | 1     | 10/02/2015     | 2048000001BN | Driveability System Diagnosis           | 46.77      |
| 936     | 0.25  | N         | 1     | 10/02/2015     | 2048MH0165BN | Driveability Misc Parts Repair          | 11.15      |
| 936     | 1.06  | N         | 1     | 10/02/2015     | 2048MH0165BN | Driveability Misc Parts Repair          | 47.65      |
| 936     | 1.17  | N         | 1     | 10/05/2015     | 2031B20100BN | Charging System Belt Alternator Replace | 52.84      |
| 936     | 0.00  | N         | 1     | 10/05/2015     | 2048MH0165BN | Driveability Misc Parts Repair          | 0.08       |

**SUBTOTAL: 158.49**

**PARTS ISSUED**

| PART NUMBER/ DESCRIPTION | S/ NS | ISS QTY | UNIT PRICE | PART ISS DATE | REPAIR TYPE  | RTY DESCRIPTION                     | PART COST |
|--------------------------|-------|---------|------------|---------------|--------------|-------------------------------------|-----------|
| AP104                    | NS    | 1       | 2.10       | 10/02/2015    | 2048000001BN | Driveability System Diagnosis       | 2.10      |
| DG508                    | NS    | 1       | 43.48      | 10/02/2015    | 2048000001BN | Driveability System Diagnosis       | 43.48     |
| r532614s                 | NS    | 1       | 3.55       | 10/02/2015    | 2048000001BN | Driveability System Diagnosis       | 3.55      |
| R532614L                 | NS    | 1       | 4.88       | 10/02/2015    | 2048000001BN | Driveability System Diagnosis       | 4.88      |
| r532614n                 | NS    | 1       | 2.77       | 10/02/2015    | 2048000001BN | Driveability System Diagnosis       | 2.77      |
| 5061230                  | NS    | 1       | 37.81      | 10/05/2015    | 2031B20100BN | Charging System Belt Alternator Rep | 37.81     |

**SUBTOTAL: 94.59**

**MISCELANEOUS COSTS**

| CODE      | DESCRIPTION                 | COST POSTED DATE | REPAIR TYPE  | RTY DESCRIPTION             | MISC COST |
|-----------|-----------------------------|------------------|--------------|-----------------------------|-----------|
| WO Charge | Flat Rate Work Order Charge | 10/05/2015       | 2020A00604BS | Work Order Flat Rate Charge | 19.02     |

**SUBTOTAL: 19.02**

**WORK ORDER TOTALS**

**TOTAL: 272.10**

**NOTES**

customer complaint is popping noise under the hood

I found #8 spark plug blown out I will install repair sleeve, 10 spark plugs and 1 coil

Shep installed spark plugs at 109K at 08.27.2012

1 each spark plug repair kit

1 each coil

1 each spark plug 6.8L v10

1 each serpentine belt Dayco 1230k6 20-9789

After installing the spark plug, coil and insert I found the serpentine belt worn... when the work was done I test driven the vehicle and all is well

# FASTER WORK ORDER PRINT

**WORK ORDER # 70445**  
**EQUIPMENT # 9604**

Date In: 12/04/2015 Date Out: 12/04/2015 Work Order Status: C Work Order Shop: W05

|                |                             |                          |                  |
|----------------|-----------------------------|--------------------------|------------------|
| COLOR: White   | COMPANY: 001                | TIRE SIZE 1: LT225X75R16 | FUEL TYPE 1: U   |
| YEAR: 2006     | DEPT: Trans/Agin            | TIRE SIZE 2: LT225X75R16 | FUEL T YPE 2:    |
| MAKE: FORD     | CLASS: 175                  | ENGINE SIZE: 6.8L        | FUEL TYPE 3:     |
| MODEL: E-350   | SITE: 175                   | TRANS: 5SPD AUTO         | EQ AVAIL CODE: 1 |
| LICENSE: 57893 | SERIAL #: 1FDWE35S96DA32014 | TITLE:                   | BILLING CODE: 1  |
| OPERATOR:      | MONITOR GROUP:              | CURRENT METERS:          | M 194,206        |

## TECHNICIAN REPAIRS PERFORMED

| TECH ID   | OVER HOURS | TIME | SHIFT | LABOR END DATE | REPAIR TYPE  | RTY DESCRIPTION                         | LABOR COST |
|-----------|------------|------|-------|----------------|--------------|---|------------|
| 963       | 0.33       | N    | 1     | 12/04/2015     | 2007BJ0100BN | Glass-Component Blade W/S Wiper Replace | 14.94      |
| SUBTOTAL: |            |      |       |                |              |   | 14.94      |

## PARTS ISSUED

| PART NUMBER/ DESCRIPTION | S/ NS | ISS QTY | UNIT PRICE | PART ISS DATE | REPAIR TYPE  | RTY DESCRIPTION                   | PART COST |
|--------------------------|-------|---------|------------|---------------|--------------|-----------------------------------|-----------|
| 700222                   | NS    | 2       | 2.05       | 12/04/2015    | 2007BJ0100BN | Glass-Component Blade W/S Wiper f | 4.10      |
| SUBTOTAL:                |       |         |            |               |              |                                   | 4.10      |

## MISCELLANEOUS COSTS

| CODE      | DESCRIPTION                 | COST POSTED DATE | REPAIR TYPE  | RTY DESCRIPTION             | MISC COST |
|-----------|-----------------------------|------------------|--------------|-----------------------------|-----------|
| WO Charge | Flat Rate Work Order Charge | 12/04/2015       | 2020A00604BS | Work Order Flat Rate Charge | 1.79      |
| SUBTOTAL: |                             |                  |              |                             | 1.79      |

WORK ORDER TOTALS

TOTAL: 20.83 ✓

## NOTES

2 each wiper blades

# Invoice



KANSAS FIRE EQUIPMENT CO., INC  
123 S. OSAGE  
WICHITA, KS 67213  
www.kansasfire.com  
(316) 262-8943

*copy*  
Invoice Number: 0421781-IN  
Invoice Date: 1/13/2016

Service #: 0001

Account No: 0045480

9684  
Bill To:

DEPT ON AGING & TRANSPORT.  
2622 W. CENTRAL #500  
ATTN: KANDACE BONNESEN  
WICHITA, KS 67203

Address Serviced:

SEDG. CO. DEPT. ON AGING & TR  
2622 W. CENTRAL #500  
WICHITA, KS 67203

Customer P.O.

Confirm To:

A149816

Terms

NET 30 DAYS

| Quantity | Item    | Description               | Price | Amount |
|----------|---------|---------------------------|-------|--------|
| 1        | /5ABC S | FIRE EXT. CHECK & SERVICE | 4.75  | 4.75   |

Vendor # 200

Doc # \_\_\_\_\_

Authorizer DS/BA

340359-16 Fe254 GL42411

Net Invoice: 4.75

Freight: 0.00

Sales Tax: 0.00

Invoice Total: 4.75

Please pay from this invoice.  
Return 1 copy of invoice with payment

LATE CHARGE: 2% FOR EACH ADDITIONAL MONTH AFTER 30 DAYS

# FASTER WORK ORDER PRINT

**WORK ORDER # 70868**  
**EQUIPMENT # 9604**

Date In: 01/21/2016 Date Out: 01/21/2016 Work Order Status: C Work Order Shop: W05

|                |                             |                          |                  |
|----------------|-----------------------------|--------------------------|------------------|
| COLOR: White   | COMPANY: 001                | TIRE SIZE 1: LT225X75R16 | FUEL TYPE 1: U   |
| YEAR: 2006     | DEPT: Trans/Agin            | TIRE SIZE 2: LT225X75R16 | FUEL T YPE 2:    |
| MAKE: FORD     | CLASS: 175                  | ENGINE SIZE: 6.8L        | FUEL TYPE 3:     |
| MODEL: E-350   | SITE: 175                   | TRANS: 5SPD AUTO         | EQ AVAIL CODE: 1 |
| LICENSE: 57893 | SERIAL #: 1FDWE35S96DA32014 | TITLE:                   | BILLING CODE: 1  |
| OPERATOR:      | MONITOR GROUP:              | CURRENT METERS:          | M 196,750        |

## TECHNICIAN REPAIRS PERFORMED

| TECH ID   | HOURS | OVER TIME | SHIFT | LABOR END DATE | REPAIR TYPE  | RTY DESCRIPTION                | LABOR COST |
|-----------|-------|-----------|-------|----------------|--------------|--------------------------------|------------|
| 936       | 0.73  | N         | 1     | 01/21/2016     | 2004MH0165BN | Heating Vent Misc Parts Repair | 32.69      |
| SUBTOTAL: |       |           |       |                |              |                                | 32.69      |

## MISCELLANEOUS COSTS

| CODE      | DESCRIPTION                 | COST POSTED DATE | REPAIR TYPE  | RTY DESCRIPTION             | MISC COST |
|-----------|-----------------------------|------------------|--------------|-----------------------------|-----------|
| WO Charge | Flat Rate Work Order Charge | 01/21/2016       | 2020A00604BS | Work Order Flat Rate Charge | 3.92      |
| SUBTOTAL: |                             |                  |              |                             | 3.92      |

|                   |        |       |
|-------------------|--------|-------|
| WORK ORDER TOTALS | TOTAL: | 36.61 |
|-------------------|--------|-------|

## NOTES

Phil, rear heater not working.

I found a blown 15 amp fuse in the fuse panel just foward of the right entry door.

I replaced it with a 20 amp fuse.

If it blows again it will need a new motor

# FASTER WORK ORDER PRINT

## WORK ORDER # 70900 EQUIPMENT # 9604

Date In: 01/26/2016 Date Out: 01/29/2016 Work Order Status: C Work Order Shop: W05

|                |                             |                          |                  |
|----------------|-----------------------------|--------------------------|------------------|
| COLOR: White   | COMPANY: 001                | TIRE SIZE 1: LT225X75R16 | FUEL TYPE 1: U   |
| YEAR: 2006     | DEPT: Trans/Agin            | TIRE SIZE 2: LT225X75R16 | FUEL T YPE 2:    |
| MAKE: FORD     | CLASS: 175                  | ENGINE SIZE: 6.8L        | FUEL TYPE 3:     |
| MODEL: E-350   | SITE: 175                   | TRANS: 5SPD AUTO         | EQ AVAIL CODE: 1 |
| LICENSE: 57893 | SERIAL #: 1FDWE35S96DA32014 | TITLE:                   | BILLING CODE: 1  |
| OPERATOR:      | MONITOR GROUP:              | CURRENT METERS:          | M 197,097        |

### TECHNICIAN REPAIRS PERFORMED

| TECH ID | HOURS | OVER TIME | SHIFT | LABOR END DATE | REPAIR TYPE  | RTY DESCRIPTION                     | LABOR COST |
|---------|-------|-----------|-------|----------------|--------------|-------------------------------------|------------|
| 936     | 1.32  | N         | 1     | 01/26/2016     | 2004BJ0165BN | Heating Vent Blade Heater Fa Repair | 59.24      |
| 936     | 0.34  | N         | 1     | 01/26/2016     | 2034LN1100BN | Light System Light Exterior Replace | 15.38      |
| 936     | 1.02  | N         | 1     | 01/26/2016     | PMA BS       | A Service List                      | 45.00      |
| 936     | 1.05  | N         | 1     | 01/26/2016     | 2004BJ0165BN | Heating Vent Blade Heater Fa Repair | 47.14      |
| 936     | 0.94  | N         | 1     | 01/29/2016     | 2004BJ0165BN | Heating Vent Blade Heater Fa Repair | 42.08      |

SUBTOTAL: 208.84

### PARTS ISSUED

| PART NUMBER/<br>DESCRIPTION | S/ NS | ISS QTY | UNIT PRICE | PART ISS DATE | REPAIR TYPE  | RTY DESCRIPTION                     | PART COST |
|-----------------------------|-------|---------|------------|---------------|--------------|-------------------------------------|-----------|
| 9007                        | NS    | 1       | 2.58       | 01/28/2016    | 2034LN1100BN | Light System Light Exterior Replace | 2.58      |
| 110008                      | NS    | 1       | 111.56     | 01/28/2016    | 2004BJ0165BN | Heating Vent Blade Heater Fa Repair | 111.56    |
| r1042                       | NS    | 1       | 1.15       | 01/26/2016    | PMA BS       | A Service List                      | 1.15      |
| 5w20                        | S     | 7       | 1.86       | 01/26/2016    | PMA BS       | A Service List                      | 13.02     |
| r1372                       | NS    | 1       | 1.32       | 01/26/2016    | PMA BS       | A Service List                      | 1.32      |
| 9007                        | NS    | 1       | 2.58       | 01/28/2016    | 2004BJ0165BN | Heating Vent Blade Heater Fa Repair | 2.58      |
| r1042                       | NS    | 1       | -1.15      | 01/26/2016    | PMA BS       | A Service List                      | -1.15     |
| 9007                        | NS    | 1       | -2.58      | 01/28/2016    | 2004BJ0165BN | Heating Vent Blade Heater Fa Repair | -2.58     |

SUBTOTAL: 128.48

### MISCELLANEOUS COSTS

| CODE      | DESCRIPTION                 | COST POSTED DATE | REPAIR TYPE  | RTY DESCRIPTION             | MISC COST |
|-----------|-----------------------------|------------------|--------------|-----------------------------|-----------|
| WO Charge | Flat Rate Work Order Charge | 01/29/2016       | 2020A00604BS | Work Order Flat Rate Charge | 25.06     |


SUBTOTAL: 25.06

WORK ORDER TOTALS

TOTAL: 362.38

NOTES

1521 S. TYLER RD  
WICHITA, KS 67209



8846 W. MONROE CIRCLE  
WICHITA, KS 67209

Tel: (316) 722-4291 • Toll Free: (800) 365-0217 • Fax: (316) 722-5917

MAINT. Charged Fleet  
9604

CUSTOMER IS WAITING


|       |     |       |
|-------|-----|-------|
| Labor | T18 | 44.00 |
|-------|-----|-------|

|                   |       |
|-------------------|-------|
| Total Labor ..... | 44.00 |
|-------------------|-------|

(Tech:18) A

|                               |       |
|-------------------------------|-------|
| Total Repair (Customer )..... | 44.00 |
|-------------------------------|-------|

340359-16 FC254 GL45104

|   |                    | W/C | INT. | CUSTOMER   |
|---|--------------------|-----|------|--|
|   |                    |     |      | Labor 44.00<br>Parts .00<br>Sublet .00<br>Shop Supplie 5.00<br>Oil/Grease .00<br>Sub Total 49.00<br>Tax .00<br>Total 49.00 |
| <b>DISCLAIMER OF WARRANTIES</b><br>Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability of fitness for a particular purpose, and neither assumes nor authorizes any person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law. |                    | .00 | .00  |  |
| X   | CUSTOMER SIGNATURE | .00 | .00  |  |
| Page 1 of 1                      Job 07688<br><br>07688  Customer Copy   |                    |     |      |  |

# FASTER WORK ORDER PRINT

**WORK ORDER # 70967**  
**EQUIPMENT # 9604**

Date In: 02/03/2016 Date Out: 02/03/2016 Work Order Status: C Work Order Shop: W05

|                |                             |                          |                  |
|----------------|-----------------------------|--------------------------|------------------|
| COLOR: White   | COMPANY: 001                | TIRE SIZE 1: LT225X75R16 | FUEL TYPE 1: U   |
| YEAR: 2006     | DEPT: Trans/Agin            | TIRE SIZE 2: LT225X75R16 | FUEL T YPE 2:    |
| MAKE: FORD     | CLASS: 175                  | ENGINE SIZE: 6.8L        | FUEL TYPE 3:     |
| MODEL: E-350   | SITE: 175                   | TRANS: 5SPD AUTO         | EQ AVAIL CODE: 1 |
| LICENSE: 57893 | SERIAL #: 1FDWE35S96DA32014 | TITLE:                   | BILLING CODE: 1  |
| OPERATOR:      | MONITOR GROUP:              | CURRENT METERS:          | M 198,027        |

## TECHNICIAN REPAIRS PERFORMED

| TECH ID   | HOURS | OVER TIME | SHIFT | LABOR END DATE | REPAIR TYPE  | RTY DESCRIPTION                       | LABOR COST |
|-----------|-------|-----------|-------|----------------|--------------|---------------------------------------|------------|
| 963       | 0.88  | N         | 1     | 02/03/2016     | 2048000001BN | Driveability System Diagnosis         | 39.51      |
| 963       | 1.16  | N         | 1     | 02/03/2016     | 2033CE0100BN | Ignition System Coil Ignition Replace | 52.23      |
| 963       | 1.64  | N         | 1     | 02/03/2016     | 2033CE0100BN | Ignition System Coil Ignition Replace | 73.90      |
| 963       | 1.52  | N         | 1     | 02/03/2016     | 2033CE0100BN | Ignition System Coil Ignition Replace | 68.56      |
| SUBTOTAL: |       |           |       |                |              |                                       | 234.20     |

## PARTS ISSUED

| PART NUMBER/ DESCRIPTION | S/ NS | ISS QTY | UNIT PRICE | PART ISS DATE | REPAIR TYPE  | RTY DESCRIPTION                       | PART COST |
|--------------------------|-------|---------|------------|---------------|--------------|---------------------------------------|-----------|
| DG508                    | NS    | 1       | 43.48      | 02/03/2016    | 2033CE0100BN | Ignition System Coil Ignition Replace | 43.48     |
| 41-812                   | NS    | 1       | 5.07       | 02/03/2016    | 2033SH0100BN | Ignition System Spark Plug Replace    | 5.07      |
| SUBTOTAL:                |       |         |            |               |              |                                       | 48.55     |

## MISCELLANEOUS COSTS

| CODE      | DESCRIPTION                 | COST POSTED DATE | REPAIR TYPE  | RTY DESCRIPTION             | MISC COST |
|-----------|-----------------------------|------------------|--------------|-----------------------------|-----------|
| WO Charge | Flat Rate Work Order Charge | 02/03/2016       | 2020A00604BS | Work Order Flat Rate Charge | 28.10     |
| SUBTOTAL: |                             |                  |              |                             | 28.10     |

|                   |        |        |
|-------------------|--------|--------|
| WORK ORDER TOTALS | TOTAL: | 310.85 |
|-------------------|--------|--------|

## NOTES

Beau, check engine light came on and was flashing. Customer said when you accelerate the RPM's go up but takes a moment or so for the vehicle to actually kick in.

P0302 - Cylinder 2 missfire

Was unable to remove plug. It was binding most likely in the sleeve. Replaced spark plug, reset KAM, and test drove. No missfires at this time.

Parts:

1 spark plug

1 Coil

02/03/2016 @ 08:26:17



# FASTER WORK ORDER PRINT

**WORK ORDER # 71065**  
**EQUIPMENT # 9604**

Date In: 02/12/2016 Date Out: 02/12/2016 Work Order Status: C Work Order Shop: W05

|                |                             |                          |                  |
|----------------|-----------------------------|--------------------------|------------------|
| COLOR: White   | COMPANY: 001                | TIRE SIZE 1: LT225X75R16 | FUEL TYPE 1: U   |
| YEAR: 2006     | DEPT: Trans/Agin            | TIRE SIZE 2: LT225X75R16 | FUEL T YPE 2:    |
| MAKE: FORD     | CLASS: 175                  | ENGINE SIZE: 6.8L        | FUEL TYPE 3:     |
| MODEL: E-350   | SITE: 175                   | TRANS: 5SPD AUTO         | EQ AVAIL CODE: 1 |
| LICENSE: 57893 | SERIAL #: 1FDWE35S96DA32014 | TITLE:                   | BILLING CODE: 1  |
| OPERATOR:      | MONITOR GROUP:              | CURRENT METERS:          | M 199,379        |

## TECHNICIAN REPAIRS PERFORMED

| TECH ID   | HOURS | OVER TIME | SHIFT | LABOR END DATE | REPAIR TYPE  | RTY DESCRIPTION                  | LABOR COST |
|-----------|-------|-----------|-------|----------------|--------------|----------------------------------|------------|
| 936       | 1.48  | N         | 1     | 02/12/2016     | 2080MH0100BN | Heating-Refer Misc Parts Replace | 66.55      |
| 936       | 1.07  | N         | 1     | 02/12/2016     | 2080MH0100BN | Heating-Refer Misc Parts Replace | 48.15      |
| 936       | 0.46  | N         | 1     | 02/12/2016     | 2080MH0100BN | Heating-Refer Misc Parts Replace | 20.71      |
| SUBTOTAL: |       |           |       |                |              |                                  | 135.41     |

## PARTS ISSUED

| PART NUMBER/ DESCRIPTION | S/ NS | ISS QTY | UNIT PRICE | PART ISS DATE | REPAIR TYPE  | RTY DESCRIPTION                  | PART COST |
|--------------------------|-------|---------|------------|---------------|--------------|----------------------------------|-----------|
| min-15                   | NS    | 1       | 1.63       | 02/12/2016    | 2080MH0100BN | Heating-Refer Misc Parts Replace | 1.63      |
| min-15                   | NS    | 1       | 1.63       | 02/12/2016    | 2080MH0100BN | Heating-Refer Misc Parts Replace | 1.63      |
| SUBTOTAL:                |       |         |            |               |              |                                  | 3.26      |

## MISCELLANEOUS COSTS

| CODE      | DESCRIPTION                 | COST POSTED DATE | REPAIR TYPE  | RTY DESCRIPTION             | MISC COST |
|-----------|-----------------------------|------------------|--------------|-----------------------------|-----------|
| WO Charge | Flat Rate Work Order Charge | 02/12/2016       | 2020A00604BS | Work Order Flat Rate Charge | 16.25     |
| SUBTOTAL: |                             |                  |              |                             | 16.25     |

WORK ORDER TOTALS

TOTAL: 154.92

## NOTES

Phil, the rear blower motor for the heater is not working again.  
found shorted wire by the rear upper door frame



# FASTER WORK ORDER PRINT

**WORK ORDER # 71253**  
**EQUIPMENT # 9604**

Date In: 03/08/2016 Date Out: 03/09/2016 Work Order Status: C Work Order Shop: W05

|                |                             |                          |                  |
|----------------|-----------------------------|--------------------------|------------------|
| COLOR: White   | COMPANY: 001                | TIRE SIZE 1: LT225X75R16 | FUEL TYPE 1: U   |
| YEAR: 2006     | DEPT: Trans/Agin            | TIRE SIZE 2: LT225X75R16 | FUEL TYPE 2:     |
| MAKE: FORD     | CLASS: 175                  | ENGINE SIZE: 6.8L        | FUEL TYPE 3:     |
| MODEL: E-350   | SITE: 175                   | TRANS: 5SPD AUTO         | EQ AVAIL CODE: 1 |
| LICENSE: 57893 | SERIAL #: 1FDWE35S96DA32014 | TITLE:                   | BILLING CODE: 1  |
| OPERATOR:      | MONITOR GROUP:              | CURRENT METERS:          | M 201,987        |

## TECHNICIAN REPAIRS PERFORMED

| TECH ID   | OVER HOURS | TIME | SHIFT | LABOR END DATE | REPAIR TYPE  | RTY DESCRIPTION                         | LABOR COST |
|-----------|------------|------|-------|----------------|--------------|---|------------|
| 927       | 0.25       | N    | 1     | 03/08/2016     | 1017TM3105BS | Tire / Tube Tire Light Replace All      | 11.10      |
| 957       | 3.87       | N    | 1     | 03/08/2016     | PMD BS       | D Service List                          | 180.00     |
| 957       | 0.48       | N    | 1     | 03/08/2016     | 1002P40040BS | Cab Panel Body Adjust                   | 21.75      |
| 957       | 0.30       | N    | 1     | 03/08/2016     | 1002P40040BS | Cab Panel Body Adjust                   | 13.58      |
| 957       | 1.18       | N    | 1     | 03/08/2016     | 1013DJ1115BS | Brake Group Disc Pad Brake Replace Rear | 53.02      |
| 957       | 3.40       | N    | 1     | 03/08/2016     | 1017TM3105BS | Tire / Tube Tire Light Replace All      | 153.21     |
| 957       | 0.29       | N    | 1     | 03/09/2016     | 3043PB0165BS | Exhaust Engine Pipe Exhaust Repair      | 12.96      |
| 957       | 0.39       | N    | 1     | 03/09/2016     | 3043PB0165BS | Exhaust Engine Pipe Exhaust Repair      | 17.58      |
| 957       | 0.76       | N    | 1     | 03/09/2016     | 1042T60100BS | Cooling Engine Tank Overflow Replace    | 34.24      |
| 957       | 0.92       | N    | 1     | 03/09/2016     | 1042T60100BS | Cooling Engine Tank Overflow Replace    | 41.45      |
| 957       | 0.76       | N    | 1     | 03/09/2016     | 1007ME0100BS | Glass-Component Mirror Replace          | 34.24      |
| 957       | 0.00       | N    | 1     | 03/09/2016     | PMD BS       | D Service List                          | 0.00       |
| SUBTOTAL: |            |      |       |                |              |   | 573.13     |

## SUBLET REPAIRS

| VENDOR                      | PARTS | LABOR | OTHER | OPID | SUBLET DATE | REPAIR TYPE  | RTY DESCRIPTION                  | SUBLET COST |
|-----------------------------|-------|-------|-------|------|-------------|--------------|----------------------------------|-------------|
| Bills American Muffler Shop | 85.00 | 0.00  | 0.00  | ch   | 03/09/2016  | 3043PB0165BS | Exhaust Engine Pipe Exhaust Repa | 85.00       |
| SUBTOTAL:                   |       |       |       |      |             |              |                                  | 85.00       |

## PARTS ISSUED

| PART NUMBER/ DESCRIPTION | S/ NS | ISS QTY | UNIT PRICE | PART ISS DATE | REPAIR TYPE  | RTY DESCRIPTION                     | PART COST |
|--------------------------|-------|---------|------------|---------------|--------------|-------------------------------------|-----------|
| f1820s                   | NS    | 1       | 3.61       | 03/08/2016    | PMD BS       | D Service List                      | 3.61      |
| p6418                    | NS    | 1       | 4.23       | 03/08/2016    | PMD BS       | D Service List                      | 4.23      |
| v3595                    | NS    | 1       | 2.35       | 03/08/2016    | PMD BS       | D Service List                      | 2.35      |
| 14d802m                  | NS    | 1       | 15.57      | 03/08/2016    | 1013DJ1115BS | Brake Group Disc Pad Brake Replace  | 15.57     |
| 8404                     | NS    | 6       | 252.13     | 03/08/2016    | 1017TM3105BS | Tire / Tube Tire Light Replace All  | 1,512.78  |
| 5w20                     | S     | 7       | 1.86       | 03/08/2016    | PMD BS       | D Service List                      | 13.02     |
| h5628q                   | NS    | 1       | 9.35       | 03/08/2016    | 1013DJ1115BS | Brake Group Disc Pad Brake Replace  | 9.35      |
| 610256                   | NS    | 1       | 22.81      | 03/09/2016    | PMD BS       | D Service List                      | 22.81     |
| 4c2z8a080bc              | NS    | 1       | 82.48      | 03/09/2016    | 1042T60100BS | Cooling Engine Tank Overflow Replac | 82.48     |
| SUBTOTAL:                |       |         |            |               |              |                                     | 1,666.20  |

## MISCELLANEOUS COSTS

| CODE      | DESCRIPTION                 | COST POSTED DATE | REPAIR TYPE  | RTY DESCRIPTION             | MISC COST |
|-----------|-----------------------------|------------------|--------------|-----------------------------|-----------|
| WO Charge | Flat Rate Work Order Charge | 03/09/2016       | 2020A00604BS | Work Order Flat Rate Charge | 68.78     |
| SUBTOTAL: |                             |                  |              |                             | 68.78     |

## FASTER WORK ORDER PRINT

**WORK ORDER # 71253**  
**EQUIPMENT # 9604**

---

WORK ORDER TOTALS

TOTAL: 2,393.11

---

NOTES

Shep, PMD. Oil change, fuel filter if it has one on the frame, and transmission flush. Spark plugs have been done.

1. PMD
2. Found rear brake pads low. Replace rear brake pads.
3. Found all 6 tires dry rotted. Replacing All 6 tires.
4. Found exhaust broken by the axle and exhaust hanger broken where it bends back to driver side. Truck going to be getting sent out to Bills American muffler for exhaust replacement.
5. Closed rear coolant hoses for spring summer.
6. Found screws loose to the wheel chair ramp door frame. Back door frame and passenger entry door frame. Tightened screws.
7. Found the coolant to be extremely dirty. The reservoir is filled up dried up residue. Cannot see the coolant level. Doing a drain and refill of coolant. Replacing coolant reservoir.
8. Found the mirror above driver seat broken and taped. Replaced mirror.

CHANGE OIL AND FILTER (6.5QTS 6.8 V10)  
LUBE SUSPENSION  
CHECK ALL EXTERIOR LIGHTS  
CHECK ALL INTERIOR LIGHTS  
INSTALL GREASE ZERKS WHEN NEEDED  
INSTALL PRIMARY FUEL FILTER  
FLUSH TRANS.

ITEMS CHECKED:

- EXHAUST SYSTEM
- TIRE PRESSURE AND TIRE CONDITION (ADD AIR IF NEEDED)
- ALL FLUID LEVELS (ADD IF NEEDED)
- SUSPENION AND STEERING PARTS
- BRAKES
- HOSES
- FOR LEAKS
- AIR FILTERS (REPLACE IF NEEDED)

6.8L V10 6.5qts 5w-20

1 each oil filter FL-820S  
1 each air filter 6418  
1 each fuel filter 33595

PLEASE ACTIVATE OIL

1 each rear brake pad set FORD E-350

6 each Michelen Ribbed LT.225/75-16C

---

1 each coolant reservoir ( DEGAS BOTTLE) FORD

---

1 each mirror 7x16 with mounting studs on end

**FASTER WORK ORDER PRINT**

**WORK ORDER # 71776  
EQUIPMENT # 9604**

Date In: 04/28/2016 Date Out: 04/28/2016 Work Order Status: C Work Order Shop: W05

|                |                             |                          |                  |
|----------------|-----------------------------|--------------------------|------------------|
| COLOR: White   | COMPANY: 001                | TIRE SIZE 1: LT225X75R16 | FUEL TYPE 1: U   |
| YEAR: 2006     | DEPT: Trans/Agin            | TIRE SIZE 2: LT225X75R16 | FUEL T YPE 2:    |
| MAKE: FORD     | CLASS: 175                  | ENGINE SIZE: 6.8L        | FUEL TYPE 3:     |
| MODEL: E-350   | SITE: 175                   | TRANS: 5SPD AUTO         | EQ AVAIL CODE: 1 |
| LICENSE: 57893 | SERIAL #: 1FDWE35S96DA32014 | TITLE:                   | BILLING CODE: 1  |
| OPERATOR:      | MONITOR GROUP:              | CURRENT METERS:          | M 206,969        |

**TECHNICIAN REPAIRS PERFORMED**

| TECH ID          | HOURS | OVER TIME | SHIFT | LABOR END DATE | REPAIR TYPE  | RTY DESCRIPTION                        | LABOR COST    |
|------------------|-------|-----------|-------|----------------|--------------|--|---------------|
| 957              | 2.02  | N         | 1     | 04/28/2016     | PMA BS       | A Service List                         | 45.00         |
| 957              | 0.40  | N         | 1     | 04/28/2016     | 1034L50001BS | Light System Brake Light Diagnosis     | 18.00         |
| 957              | 0.96  | N         | 1     | 04/28/2016     | 1034L50166BS | Light System Brake Light Repair Wiring | 43.24         |
| 957              | 0.59  | N         | 1     | 04/28/2016     | 1002DP3165BS | Cab Door Entrance Repair               | 26.69         |
| 957              | 0.00  | N         | 1     | 04/28/2016     | 1034L50166BS | Light System Brake Light Repair Wiring | 0.06          |
| 957              | 1.49  | N         | 1     | 04/28/2016     | 1002DP3165BS | Cab Door Entrance Repair               | 67.26         |
| <b>SUBTOTAL:</b> |       |           |       |                |              |  | <b>200.25</b> |

**PARTS ISSUED**

| PART NUMBER/ DESCRIPTION | S/ NS | ISS QTY | UNIT PRICE | PART ISS DATE | REPAIR TYPE | RTY DESCRIPTION | PART COST    |
|--------------------------|-------|---------|------------|---------------|-------------|-----------------|--------------|
| f1820s                   | NS    | 1       | 3.61       | 04/28/2016    | PMA BS      | A Service List  | 3.61         |
| 5w20                     | S     | 7       | 1.86       | 04/28/2016    | PMA BS      | A Service List  | 13.02        |
| 80855                    | NS    | 3       | 13.26      | 04/28/2016    | PMA BS      | A Service List  | 39.78        |
| <b>SUBTOTAL:</b>         |       |         |            |               |             |                 | <b>56.41</b> |

**MISCELLANEOUS COSTS**

| CODE             | DESCRIPTION                 | COST POSTED DATE | REPAIR TYPE  | RTY DESCRIPTION             | MISC COST    |
|------------------|-----------------------------|------------------|--------------|-----------------------------|--------------|
| WO Charge        | Flat Rate Work Order Charge | 04/28/2016       | 2020A00604BS | Work Order Flat Rate Charge | 24.03        |
| <b>SUBTOTAL:</b> |                             |                  |              |                             | <b>24.03</b> |

WORK ORDER TOTALS

**TOTAL: 280.69**

NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 71776**  
**EQUIPMENT # 9604**

9604- Shep.

1. PMA.
2. Found 3rd brake light not working. Wire had broke loose. Installed built connectors.
3. When pulled the trim down in the back to repair the 3rd brake light. Found water sitting in the trim. The right corner of roof had leaked, where the wheel chair lift door was at. Found gaps in the seals on the edge. Put silicone in around the seal. Found wood damage to the trim pieces. due to water. intsalled. longer screws to keep the trim pieces together.

CHANGE OIL AND FILTER (6.5QTS 6.8L V10)

LUBE SUSPENSION

CHECK ALL EXTERIOR LIGHTS

CHECK ALL INTERIOR LIGHTS

INSTALL GREASE ZERKS WHEN NEEDED

CHECK WHEEL CHAIR LIFT

ITEMS CHECKED:

- EXHAUST SYSTEM
- TIRE PRESSURE AND TIRE CONDITION (ADD AIR IF NEEDED)
- ALL FLUID LEVELS (ADD IF NEEDED)
- SUSPENION AND STEERING PARTS
- BRAKES
- BELTS
- HOSES
- FOR LEAKS
- AIR FILTERS (REPLACE IF NEEDED)
- CHECK BATTERIES (REPLACE IF NEEDED)

6.8L V10 6.5qts 5w-20

1 each oil filter FL-820S

PLEASE ACTIVATE OIL

**FASTER WORK ORDER PRINT**

**WORK ORDER # 71871  
EQUIPMENT # 9604**

Date In: 05/06/2016 Date Out: 05/06/2016 Work Order Status: C Work Order Shop: W05

|                |                             |                          |                  |
|----------------|-----------------------------|--------------------------|------------------|
| COLOR: White   | COMPANY: 001                | TIRE SIZE 1: LT225X75R16 | FUEL TYPE 1: U   |
| YEAR: 2006     | DEPT: Trans/Agin            | TIRE SIZE 2: LT225X75R16 | FUEL T YPE 2:    |
| MAKE: FORD     | CLASS: 175                  | ENGINE SIZE: 6.8L        | FUEL TYPE 3:     |
| MODEL: E-350   | SITE: 175                   | TRANS: 5SPD AUTO         | EQ AVAIL CODE: 1 |
| LICENSE: 57893 | SERIAL #: 1FDWE35S96DA32014 | TITLE:                   | BILLING CODE: 1  |
| OPERATOR:      | MONITOR GROUP:              | CURRENT METERS:          | M 208,283        |

TECHNICIAN REPAIRS PERFORMED

| TECH ID   | HOURS | OVER TIME | SHIFT | LABOR END DATE | REPAIR TYPE  | RTY DESCRIPTION                    | LABOR COST |
|-----------|-------|-----------|-------|----------------|--------------|------------------------------------|------------|
| 927       | 0.00  | N         | 1     | 05/06/2016     | 2041MH0100BN | Air Intake Engi Misc Parts Replace | 0.04       |
| SUBTOTAL: |       |           |       |                |              |                                    | 0.04       |

PARTS ISSUED

| PART NUMBER/ DESCRIPTION | S/ NS | ISS QTY | UNIT PRICE | PART ISS DATE | REPAIR TYPE  | RTY DESCRIPTION                    | PART COST |
|--------------------------|-------|---------|------------|---------------|--------------|------------------------------------|-----------|
| fa1632                   | NS    | 1       | 11.83      | 05/06/2016    | 2041MH0100BN | Air Intake Engi Misc Parts Replace | 11.83     |
| SUBTOTAL:                |       |         |            |               |              |                                    | 11.83     |

WORK ORDER TOTALS

TOTAL: 11.87

NOTES

9604,  
1. The air filter was not OEM. We are switching all the air filters of 6.8L engines to Motorcraft.  
Mark.  
1 each air filter FA-1632

**FASTER WORK ORDER PRINT**

**WORK ORDER # 71872**  
**EQUIPMENT # 9604**

Date In: 05/06/2016 Date Out: 05/09/2016 Work Order Status: C Work Order Shop: W05

|                |                             |                          |                  |
|----------------|-----------------------------|--------------------------|------------------|
| COLOR: White   | COMPANY: 001                | TIRE SIZE 1: LT225X75R16 | FUEL TYPE 1: U   |
| YEAR: 2006     | DEPT: Trans/Agin            | TIRE SIZE 2: LT225X75R16 | FUEL T YPE 2:    |
| MAKE: FORD     | CLASS: 175                  | ENGINE SIZE: 6.8L        | FUEL TYPE 3:     |
| MODEL: E-350   | SITE: 175                   | TRANS: 5SPD AUTO         | EQ AVAIL CODE: 1 |
| LICENSE: 57893 | SERIAL #: 1FDWE35S96DA32014 | TITLE:                   | BILLING CODE: 1  |
| OPERATOR:      | MONITOR GROUP:              | CURRENT METERS:          | M 208,343        |

**TECHNICIAN REPAIRS PERFORMED**

| TECH ID   | HOURS | OVER TIME | SHIFT | LABOR END DATE | REPAIR TYPE  | RTY DESCRIPTION                  | LABOR COST |
|-----------|-------|-----------|-------|----------------|--------------|----------------------------------|------------|
| 936       | 2.35  | N         | 1     | 05/09/2016     | 2045A00001BN | Engine Block Assembly Diagnosis  | 105.94     |
| 936       | 0.15  | N         | 1     | 05/09/2016     | 2001000001BN | Air Conditionin System Diagnosis | 6.64       |
| SUBTOTAL: |       |           |       |                |              |                                  | 112.58     |

**MISCELLANEOUS COSTS**

| CODE      | DESCRIPTION                 | COST POSTED DATE | REPAIR TYPE  | RTY DESCRIPTION             | MISC COST |
|-----------|-----------------------------|------------------|--------------|-----------------------------|-----------|
| WO Charge | Flat Rate Work Order Charge | 05/09/2016       | 2020A00604BS | Work Order Flat Rate Charge | 13.51     |
| SUBTOTAL: |                             |                  |              |                             | 13.51     |

|                   |        |        |
|-------------------|--------|--------|
| WORK ORDER TOTALS | TOTAL: | 126.09 |
|-------------------|--------|--------|

**NOTES**

Please check and advise.... The rear A/C not working and there is a ticking noise coming from the engine. The customer would like an estimate before repairs are performed. DOT funding may not cover this vehicle anymore

If there are any other obvious problems with this vehicle at this time, please note that as well

The engine has a ticking noise but not real loud Possible oil flush could work but if not due to age and mileage a new engine would be best. The rear A/C is low on Freon, I will recharge and check for leaks. I recommend a Seafoam flush at the next oil change

After recharge the rear A/C system the A/C is workning good

The rear A/C charge ports are under the dog house on the left rear corner of the engine.

I could not find any leaks at this time.

If the flush does not work then I recommend a new engine  
25.1 habor hours + engnie and misc parts and fluids

Kim can you get a price on a new engnie assembly

New long block from ford \$4000. week out



# FASTER WORK ORDER PRINT

DATE: 08/11/2016 11:05

## WORK ORDER # 72560 EQUIPMENT # 9604

Date In: 07/14/2016 Date Out: 07/14/2016 Work Order Status: C Work Order Shop: W05

|                |                             |                          |                  |
|----------------|-----------------------------|--------------------------|------------------|
| COLOR: White   | COMPANY: 001                | TIRE SIZE 1: LT225X75R16 | FUEL TYPE 1: U   |
| YEAR: 2006     | DEPT: Trans/Agin            | TIRE SIZE 2: LT225X75R16 | FUEL T YPE 2:    |
| MAKE: FORD     | CLASS: 175                  | ENGINE SIZE: 6.8L        | FUEL TYPE 3:     |
| MODEL: E-350   | SITE: 175                   | TRANS: 5SPD AUTO         | EQ AVAIL CODE: 1 |
| LICENSE: 57893 | SERIAL #: 1FDWE35S96DA32014 | TITLE:                   | BILLING CODE: 1  |
| OPERATOR:      | MONITOR GROUP:              | CURRENT METERS:          | M 209,269        |

### TECHNICIAN REPAIRS PERFORMED

| TECH ID   | HOURS | OVER TIME | SHIFT | LABOR END DATE | REPAIR TYPE  | RTY DESCRIPTION                 | LABOR COST |
|-----------|-------|-----------|-------|----------------|--------------|---------------------------------|------------|
| 957       | 3.52  | N         | N     | 07/14/2016     | 2001A00165BN | Air Conditionin Assembly Repair | 158.57     |
| SUBTOTAL: |       |           |       |                |              |                                 | 158.57     |

### PARTS ISSUED

| PART NUMBER/ DESCRIPTION | S/ NS | ISS QTY | UNIT PRICE | PART ISS DATE | REPAIR TYPE  | RTY DESCRIPTION                         | PART COST |
|--------------------------|-------|---------|------------|---------------|--------------|---|-----------|
| 700220                   | NS    | 2       | 2.22       | 07/14/2016    | 2007WP0100BN | Glass-Component Wiper Windshiel Replace | 4.44      |
| SUBTOTAL:                |       |         |            |               |              |   | 4.44      |

### MISCELLANEOUS COSTS

| CODE      | DESCRIPTION                 | COST POSTED DATE | REPAIR TYPE  | RTY DESCRIPTION             | MISC COST |
|-----------|-----------------------------|------------------|--------------|-----------------------------|-----------|
| WO Charge | Flat Rate Work Order Charge | 07/14/2016       | 2020A00604BS | Work Order Flat Rate Charge | 19.03     |
| SUBTOTAL: |                             |                  |              |                             | 19.03     |

|                   |        |        |
|-------------------|--------|--------|
| WORK ORDER TOTALS | TOTAL: | 182.04 |
|-------------------|--------|--------|

### NOTES

Shep, driver says front and rear air not cooling well. The front felt cold to me but the rear acts like its low on freon. Evacuate and recharge.

Recharged front ac. It was blowing cold. Checked rear. Was low. Evac. Vacuum and recharged. 5.31 lbs. for rear 2 for front. Found rear valve cores leaking and line leaking at hose clamps. Replaced valve cores. and tightened clamps. Working properly. Vents blowing 44 degrees out. Both front and rear.

Sedgwick County Fleet Management  
3300.rpt

# FASTER WORK ORDER PRINT

PAGE: 1

DATE: 09/02/2016 15:48

WORK ORDER # 73070  
EQUIPMENT # 9602

18-03-Aug

Date In: 08/30/2016 Date Out: None Work Order Status: V Work Order Shop: W05

|                      |                             |                 |                  |
|----------------------|-----------------------------|-----------------|------------------|
| COLOR: White         | COMPANY: 001                | TIRE SIZE 1:    | FUEL TYPE 1: U   |
| YEAR: 2016           | DEPT: Trans/Agin            | TIRE SIZE 2:    | FUEL TYPE 2:     |
| MAKE: DODGE          | CLASS: 164                  | ENGINE SIZE:    | FUEL TYPE 3:     |
| MODEL: Grand Caravan | SITE: 164                   | TRANS:          | EQ AVAIL CODE: 1 |
| LICENSE: 88052       | SERIAL #: 2C7WDGBG7GR144259 | TITLE:          | BILLING CODE: 1  |
| OPERATOR:            | MONITOR GROUP:              | CURRENT METERS: | M 15             |

## TECHNICIAN REPAIRS PERFORMED

| TECH ID | HOURS | OVER TIME | SHIFT | LABOR END DATE | REPAIR TYPE  | RTY DESCRIPTION               | LABOR COST |
|---------|-------|-----------|-------|----------------|--------------|-------------------------------|------------|
| 936     | 0.56  | N         | N     | 09/02/2016     | S016000502BN | Suspension System Travel Time | 25.41      |
| 963     | 0.41  | N         | N     | 08/30/2016     | S016000502BN | Suspension System Travel Time | 18.63      |

SUBTOTAL: 44.04

WORK ORDER TOTALS

TOTAL: 44.04

## NOTES

Beau, take to Davis Moore Dodge for noise in the left rear suspension. May be left rear shock.

Also has brake pulsation

Will be taken to Gregory Graphics in Buhler Kansas on Tuesday September 6th. We will need to take it back to the dealer for the brake rotor replacement when it gets back.

09/02/2016 @ 15:19:35