

FASTER WORK ORDER PRINT

DATE: 11/04/2015 09:51

WORK ORDER # 69833
EQUIPMENT # 9606

Date In: 09/29/2015 Date Out: 10/01/2015 Work Order Status: C Work Order Shop: W05

COLOR:	COMPANY: 001	TIRE SIZE 1:	FUEL TYPE 1: U
YEAR: 2012	DEPT: Transport	TIRE SIZE 2:	FUEL TYPE 2:
MAKE: FORD	CLASS: 175	ENGINE SIZE:	FUEL TYPE 3:
MODEL: E-350	SITE: 175	TRANS:	EQ AVAIL CODE: 1
LICENSE: temp	SERIAL #: 1FDEE3FS0CDA67417	TITLE:	BILLING CODE: 1
OPERATOR:	MONITOR GROUP:	CURRENT METERS:	M 111,534

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
957	1.38	N	1	09/29/2015	PMB BS	B Service List	58.50
957	1.49	N	1	09/29/2015	1027MH0165BS	Transmission Au Misc Parts Repair	66.86
957	0.91	N	1	09/29/2015	1027MH0165BS	Transmission Au Misc Parts Repair	40.73
957	0.90	N	1	09/29/2015	PMB BS	B Service List	0.00
957	0.19	N	1	09/29/2015	1007BJ0100BS	Glass-Component Blade W/S Wiper Replace	8.61
957	0.93	N	1	09/30/2015	1034LN1100BS	Light System Light Exterior Replace	41.95
957	3.27	N	1	09/30/2015	1013DJ1110BS	Brake Group Disc Pad Brake Replace Front	147.23
957	2.92	N	1	09/30/2015	1013DJ1115BS	Brake Group Disc Pad Brake Replace Rear	131.20
957	0.44	N	1	09/30/2015	1013AB1040BS	Brake Group Adjuster Brake Adjust	19.84
957	2.04	N	1	10/01/2015	1013C11115BS	Brake Group Caliper Brake Replace Rear	91.76
957	3.43	N	1	10/01/2015	1013C11115BS	Brake Group Caliper Brake Replace Rear	154.22
SUBTOTAL:							760.90

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
f1820s	NS	1	3.61	09/29/2015	PMB BS	B Service List	3.61
p6418	NS	1	3.83	09/29/2015	PMB BS	B Service List	3.83
brf115	NS	2	112.03	09/29/2015	1013DJ1110BS	Brake Group Disc Pad Brake Replace	224.06
brs93	NS	2	16.08	09/29/2015	1013DJ1110BS	Brake Group Disc Pad Brake Replace	32.16
bc2z25522a	NS	1	84.55	10/01/2015	1013C11115BS	Brake Group Caliper Brake Replace F	84.55
bc2z2553a	NS	1	84.55	10/01/2015	1013C11115BS	Brake Group Caliper Brake Replace F	84.55
eoaz21498	NS	2	0.92	10/01/2015	1013C11115BS	Brake Group Caliper Brake Replace F	1.84
bc2z2c150a	NS	1	21.12	10/01/2015	1013C11115BS	Brake Group Caliper Brake Replace F	21.12
brf1328	NS	1	59.11	09/29/2015	1013DJ1110BS	Brake Group Disc Pad Brake Replace	59.11
700220	NS	2	2.22	09/29/2015	PMB BS	B Service List	4.44
46743	NS	1	2.70	09/29/2015	1034LN1100BS	Light System Light Exterior Replace	2.70
5w20	S	7	1.86	09/29/2015	PMB BS	B Service List	13.02
brsd1329	NS	1	72.81	09/30/2015	1013DJ1110BS	Brake Group Disc Pad Brake Replace	72.81
c8tz1131c	NS	2	5.15	09/30/2015	PMB BS	B Service List	10.30
SUBTOTAL:							618.10

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
WO Charge	Flat Rate Work Order Charge	10/02/2015	2020A00604BS	Work Order Flat Rate Charge	91.31
SUBTOTAL:					91.31

WORK ORDER TOTALS

TOTAL: 1,470.31

FASTER WORK ORDER PRINT

**WORK ORDER # 69833
EQUIPMENT # 9606**

NOTES

Shep, PMB. Fill out KDOT book. It should be in the vehicle somewhere.

1. PMB
2. Replace wiper blades
3. RF park light out and top left clearance light out.
4. Fill out DOT book. Look up information and fill out since last dated
5. Flush transmission
6. Replace front and rear brakes
7. Replace rear calipers

CHANGE OIL AND FILTER (6.5QTS 6.8 V10)

LUBE SUSPENSION
LUBE ALL LATCHES
CHECK ALL EXTERIOR LIGHTS
CHECK ALL INTERIOR LIGHTS
INSTALL GREASE ZERKS WHEN NEEDED
INSTALL PRIMARY FUEL FILTER (DIESEL ONLY)
CHECK PATIENT AIR FILTER CLEAN IF NEEDED

ITEMS CHECKED:

- EXHAUST SYSTEM
- TIRE PRESSURE AND TIRE CONDITION (ADD AIR IF NEEDED)
- ALL FLUID LEVELS (ADD IF NEEDED)
- SUSPENION AND STEERING PARTS
- BRAKES
- BELTS
- HOSES
- FOR LEAKS
- AIR FILTERS (REPLACE IF NEEDED)
- CHECK BATTERIES (REPLACE IF NEEDED)

6.8L V10 6.5qts 5w-20

1 each oil filter FL-820S
1 each air filter 6418

PLEASE ACTIVATE OIL

FORD this is a E-350 dont know if parts are the same as ambulance

- 2 each front brake rotors
2 each front wheel seals
1 each front brake pad set
1 each brake brake pad set

1 each clearance light bringing sample

2 each 20in wiper blades

2 each C8TZ-1131 CAP FORD

1 each left rear caliper
1 each right rear caliper

1 each rear caliper pin kit

1 each package EOAZ-2149-B gasket

FASTER WORK ORDER PRINT

WORK ORDER # 70312 EQUIPMENT # 9606

Date In: 11/19/2015 Date Out: 11/19/2015 Work Order Status: C Work Order Shop: W05

COLOR:	COMPANY: 001	TIRE SIZE 1:	FUEL TYPE 1: U
YEAR: 2012	DEPT: Transport	TIRE SIZE 2:	FUEL T YPE 2:
MAKE: FORD	CLASS: 175	ENGINE SIZE:	FUEL TYPE 3:
MODEL: E-350	SITE: 175	TRANS:	EQ AVAIL CODE: 1
LICENSE: temp	SERIAL #: 1FDEE3FS0CDA67417	TITLE:	BILLING CODE: 1
OPERATOR:	MONITOR GROUP:	CURRENT METERS:	M 117,143

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
957	0.93	N	1	11/19/2015	PMC BS	C Service List	103.50
957	0.90	N	1	11/19/2015	1017TM3001BS	Tire / Tube Tire Light Diagnosis	40.51
957	0.16	N	1	11/19/2015	PMC BS	C Service List	0.00
SUBTOTAL:							144.01

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
f1820s	NS	1	3.61	11/19/2015	PMA BS	A Service List	3.61
5w20	S	6	1.86	11/19/2015	PMA BS	A Service List	11.16
SUBTOTAL:							14.77

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
WO Charge	Flat Rate Work Order Charge	11/19/2015	2020A00604BS	Work Order Flat Rate Charge	17.28
SUBTOTAL:					17.28

WORK ORDER TOTALS	TOTAL:	176.06
-------------------	--------	--------

NOTES

FASTER WORK ORDER PRINT

WORK ORDER # 70312
EQUIPMENT # 9606

9606- Shep

1. PMC-
2. LRO tire is low. Found leaking valve stem. Replaced stem.
3. Opened up rear valves for heat.

CHANGE OIL AND FILTER (6.5QTS 6.8L V10)
LUBE SUSPENSION
CHECK ALL EXTERIOR LIGHTS
CHECK ALL INTERIOR LIGHTS
INSTALL GREASE ZERKS WHEN NEEDED
CHECK PATIENT AIR FILTER CLEAN IF NEEDED

ITEMS CHECKED:

- EXHAUST SYSTEM
- TIRE PRESSURE AND TIRE CONDITION (ADD AIR IF NEEDED)
- ALL FLUID LEVELS (ADD IF NEEDED)
- SUSPENSION AND STEERING PARTS
- BRAKES
- BELTS
- HOSES
- FOR LEAKS
- AIR FILTERS (REPLACE IF NEEDED)
- CHECK BATTERIES (REPLACE IF NEEDED)

6.8L V10 6.5qts 5w-20

1 each oil filter FL-820S

PLEASE ACTIVATE OIL

FASTER WORK ORDER PRINT

DATE: 02/05/2016 09:52

WORK ORDER # 70433
EQUIPMENT # 9606

Jan 2 Net \$139.29

Date In: 12/03/2015 Date Out: 01/07/2016 Work Order Status: C Work Order Shop: W05

COLOR:	COMPANY: 001	TIRE SIZE 1:	FUEL TYPE 1: U
YEAR: 2012	DEPT: Transport	TIRE SIZE 2:	FUEL TYPE 2:
MAKE: FORD	CLASS: 175	ENGINE SIZE:	FUEL TYPE 3:
MODEL: E-350	SITE: 175	TRANS:	EQ AVAIL CODE: 1
LICENSE: temp	SERIAL #: 1FDEE3FS0CDA67417	TITLE:	BILLING CODE: 1
OPERATOR:	MONITOR GROUP:	CURRENT METERS:	M 122,600

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
936	0.11	N	1	01/05/2016	2007ME0165BN	Glass-Component Mirror Repair	5.04
936	1.11	N	1	01/05/2016	PMA BS	A Service List	45.00
936	0.13	N	1	01/05/2016	2007ME0165BN	Glass-Component Mirror Repair	5.91
936	0.68	N	1	01/07/2016	2007ME0165BN	Glass-Component Mirror Repair	30.47
936	0.48	N	1	01/07/2016	2007ME0165BN	Glass-Component Mirror Repair	21.55
957	1.09	N	1	12/03/2015	2007ME0165BN	Glass-Component Mirror Repair	49.02
SUBTOTAL:							156.99

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
130-40	NS	1	503.59	12/23/2015	2007ME0165BN	Glass-Component Mirror Repair	503.59
cs0037128	NS	1	234.88	12/23/2015	2007ME0165BN	Glass-Component Mirror Repair	234.88
frt	NS	1	27.56	12/23/2015	2053000000BN	Expendable System Misc	27.56
r1372	NS	1	1.32	01/05/2016	PMA BS	A Service List	1.32
5w20	S	6	1.86	01/05/2016	PMA BS	A Service List	11.16
SUBTOTAL:							778.51

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
WO Charge	Flat Rate Work Order Charge	01/07/2016	2020A00604BS	Work Order Flat Rate Charge	18.84
SUBTOTAL:					18.84

WORK ORDER TOTALS

TOTAL: 954.34

NOTES

FASTER WORK ORDER PRINT

WORK ORDER # 70433
EQUIPMENT # 9606

Shep, outside mirror broken. See if it can be welded up and then order a new one or see how long it will take to get one first.

Welded mirror. Ordered new one. Waiting on mirror

Mirror received on 12/23 and given to Shep....Chris

PMA

CURRENT IDLE HOURS

INSTALL MILEAGE DECAL DONE

RE-SET OIL LIFE

CHANGE OIL AND FILTER

LUBE SUSPENSION

INSTALL GREASE ZERKS WHEN NEEDED

ITEMS CHECKED:

- EXHAUST SYSTEM
- TIRE PRESSURE AND TIRE CONDITION (ADD AIR IF NEEDED)
- ALL FLUID LEVELS (ADD IF NEEDED)
- SUSPENSION AND STEERING PARTS
- BRAKES
- BELTS
- HOSES
- LEAKS
- AIR FILTER (REPLACE IF NEEDED)
- CHECK BATTERY

1 each oil filter 1372

7 Quarts of oil 5-20

Oil change was done at 122,600 miles

Pressed for time today. They need the bus back shortly. We will install the mirror assembly at another date.
01/05/2016 @ 10:54:50

FASTER WORK ORDER PRINT

WORK ORDER # 70433
EQUIPMENT # 9606

DATE: 01/06/2016 16:14

Dec 2015 \$815.05

Date In: 12/03/2015 Date Out: None Work Order Status: X Work Order Shop: W05

COLOR:	COMPANY: 001	TIRE SIZE 1:	FUEL TYPE 1: U
YEAR: 2012	DEPT: Transport	TIRE SIZE 2:	FUEL TYPE 2:
MAKE: FORD	CLASS: 175	ENGINE SIZE:	FUEL TYPE 3:
MODEL: E-350	SITE: 175	TRANS:	EQ AVAIL CODE: 1
LICENSE: temp	SERIAL #: 1FDEE3FS0CDA67417	TITLE:	BILLING CODE: 1
OPERATOR:	MONITOR GROUP:	CURRENT METERS:	M 122,600

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
936	0.11	N	1	01/05/2016	2007ME0165BN	Glass-Component Mirror Repair	5.04
936	1.11	N	1	01/05/2016	PMA BS	A Service List	45.00
936	0.13	N	1	01/05/2016	2007ME0165BN	Glass-Component Mirror Repair	5.91
957	1.09	N	1	12/03/2015	2007ME0165BN	Glass-Component Mirror Repair	49.02
SUBTOTAL:							104.97

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
130-40	NS	1	503.59	12/23/2015	2007ME0165BN	Glass-Component Mirror Repair	503.59
cs0037128	NS	1	234.88	12/23/2015	2007ME0165BN	Glass-Component Mirror Repair	234.88
frt	NS	1	27.56	12/23/2015	2053000000BN	Expendable System Misc	27.56
r1372	NS	1	1.32	01/05/2016	PMA BS	A Service List	1.32
5w20	S	6	1.86	01/05/2016	PMA BS	A Service List	11.16
SUBTOTAL:							778.51

WORK ORDER TOTALS

TOTAL: 883.48

NOTES

**The items dated 2016 will be billed January 2016 - \$68.43*

FASTER WORK ORDER PRINT

WORK ORDER # 70433
EQUIPMENT # 9606

Shep, outside mirror broken. See if it can be welded up and then order a new one or see how long it will take to get one first.

Welded mirror. Ordered new one. Waiting on mirror

Mirror received on 12/23 and given to Shep....Chris

PMA

CURRENT IDLE HOURS

INSTALL MILEAGE DECAL DONE

RE-SET OIL LIFE

CHANGE OIL AND FILTER

LUBE SUSPENSION

INSTALL GREASE ZERKS WHEN NEEDED

ITEMS CHECKED:

- EXHAUST SYSTEM
- TIRE PRESSURE AND TIRE CONDITION (ADD AIR IF NEEDED)
- ALL FLUID LEVELS (ADD IF NEEDED)
- SUSPENSION AND STEERING PARTS
- BRAKES
- BELTS
- HOSES
- LEAKS
- AIR FILTER (REPLACE IF NEEDED)
- CHECK BATTERY

1 each oil filter 1372

7 Quarts of oil 5-20

Oil change was done at 122,600 miles

Pressed for time today. They need the bus back shortly. We will install the mirror assembly at another date.
01/05/2016 @ 10:54:50

FASTER WORK ORDER PRINT

WORK ORDER # 71102 EQUIPMENT # 9606

Date In: 02/18/2016 Date Out: 02/18/2016 Work Order Status: C Work Order Shop: W05

COLOR:	COMPANY: 001	TIRE SIZE 1:	FUEL TYPE 1: U
YEAR: 2012	DEPT: Transport	TIRE SIZE 2:	FUEL T YPE 2:
MAKE: FORD	CLASS: 175	ENGINE SIZE:	FUEL TYPE 3:
MODEL: E-350	SITE: 175	TRANS:	EQ AVAIL CODE: 1
LICENSE: temp	SERIAL #: 1FDEE3FS0CDA67417	TITLE:	BILLING CODE: 1
OPERATOR:	MONITOR GROUP:	CURRENT METERS:	M 127,929

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
936	1.14	N	1	02/18/2016	PMA BS	A Service List	45.00
SUBTOTAL:							45.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
f1820s	NS	1	3.61	02/18/2016	PMA BS	A Service List	3.61
5w20	S	5	1.86	02/18/2016	PMA BS	A Service List	9.30
SUBTOTAL:							12.91

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
WO Charge	Flat Rate Work Order Charge	02/18/2016	2020A00604BS	Work Order Flat Rate Charge	5.40
SUBTOTAL:					5.40

WORK ORDER TOTALS	TOTAL:	63.31
-------------------	--------	-------

NOTES

Sedgwick County Fleet Management
3300.rpt

FASTER WORK ORDER PRINT

PAGE: 2
DATE: 03/07/2016 14:00

WORK ORDER # 71102
EQUIPMENT # 9606

Phil, pma.
PMA

CURRENT IDLE HOURS

INSTALL MILEAGE DECAL

RE-SET OIL LIFE

CHANGE OIL AND FILTER
LUBE SUSPENSION
INSTALL GREASE ZERKS WHEN NEEDED

ITEMS CHECKED:

- EXHAUST SYSTEM
- TIRE PRESSURE AND TIRE CONDITION (ADD AIR IF NEEDED)
- ALL FLUID LEVELS (ADD IF NEEDED)
- SUSPENSION AND STEERING PARTS
- BRAKES
- BELTS
- HOSES
- LEAKS
- AIR FILTER (REPLACE IF NEEDED)
- CHECK BATTERY

1 each oil filter

Quarts of oil 5-20

FASTER WORK ORDER PRINT

WORK ORDER # 71208
EQUIPMENT # 9606

Date In: 03/01/2016 Date Out: 03/02/2016 Work Order Status: C Work Order Shop: W05

COLOR:	COMPANY: 001	TIRE SIZE 1:	FUEL TYPE 1: U
YEAR: 2012	DEPT: Transport	TIRE SIZE 2:	FUEL T YPE 2:
MAKE: FORD	CLASS: 175	ENGINE SIZE:	FUEL TYPE 3:
MODEL: E-350	SITE: 175	TRANS:	EQ AVAIL CODE: 1
LICENSE: temp	SERIAL #: 1FDEE3FS0CDA67417	TITLE:	BILLING CODE: 1
OPERATOR:	MONITOR GROUP:	CURRENT METERS:	M 129,639

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
936	1.02	N	1	03/02/2016	2004BL1165BN	Heating Vent Blower Vent Repair	45.98
936	0.69	N	1	03/02/2016	2048000001BN	Driveability System Diagnosis	30.83
SUBTOTAL:							76.81

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
WO Charge	Flat Rate Work Order Charge	03/02/2016	2020A00604BS	Work Order Flat Rate Charge	9.22
SUBTOTAL:					9.22

WORK ORDER TOTALS

TOTAL: 86.03

NOTES

Phil, has a high idle at times. Rear heater not working.

I could not get the engine to act up at this time.... I scanned for codes and could find any. I checked for loose connection and did not find any.

The rear heater is working fine at this time... The blower is functioning on low and high speeds and the heat coming out is hot.

After test driving this vehicle I could not find any problems at this time

FASTER WORK ORDER PRINT

WORK ORDER # 71415
EQUIPMENT # 9606

Date In: 03/25/2016 Date Out: 03/25/2016 Work Order Status: C Work Order Shop: W05

COLOR:	COMPANY: 001	TIRE SIZE 1:	FUEL TYPE 1: U
YEAR: 2012	DEPT: Transport	TIRE SIZE 2:	FUEL T YPE 2:
MAKE: FORD	CLASS: 175	ENGINE SIZE:	FUEL TYPE 3:
MODEL: E-350	SITE: 175	TRANS:	EQ AVAIL CODE: 1
LICENSE: temp	SERIAL #: 1FDEE3FS0CDA67417	TITLE:	BILLING CODE: 1
OPERATOR:	MONITOR GROUP:	CURRENT METERS:	M 132,791

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
936	1.30	N	1	03/25/2016	PMB BS	B Service List	58.50
SUBTOTAL:							58.50

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
f1820s	NS	1	3.61	03/25/2016	PMB BS	B Service List	3.61
5w20	S	7	1.86	03/25/2016	PMB BS	B Service List	13.02
SUBTOTAL:							16.63

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
WO Charge	Flat Rate Work Order Charge	03/25/2016	2020A00604BS	Work Order Flat Rate Charge	7.02
SUBTOTAL:					7.02

WORK ORDER TOTALS	TOTAL:	82.15
-------------------	--------	-------

NOTES

FASTER WORK ORDER PRINT

WORK ORDER # 71415
EQUIPMENT # 9606

Phil, PMB.
PMB

CURRENT IDLE HOURS N/A

INSTALL MILEAGE DECAL DONE

RE-SET OIL LIFE N/A

CHANGE OIL AND FILTER

LUBE SUSPENSION

INSTALL GREASE ZERKS WHEN NEEDED

REPLACE FUEL FILTER if applicable

ITEMS CHECKED:

- EXHAUST SYSTEM
- TIRE PRESSURE AND TIRE CONDITION (ADD AIR IF NEEDED)
- LF TREAD DEPTH 10/32
- RF TREAD DEPTH 10/32
- LR TREAD DEPTH 09/32, 09/32
- RR TREAD DEPTH 09/32, 09/32
- ALL FLUID LEVELS (ADD IF NEEDED)
- SUSPENSION AND STEERING PARTS
- FRONT BRAKES ESTIMATE REMAINING 75%
- REAR BRAKES ESTIMATE REMAINING 75%
- BELTS
- HOSES
- LEAKS
- AIR FILTER (REPLACE IF NEEDED)
- CHECK BATTERY
-

1 each oil filter

7 Quarts of oil 5-20

FASTER WORK ORDER PRINT

WORK ORDER # 71732 EQUIPMENT # 9606

Date In: 04/25/2016 Date Out: 04/26/2016 Work Order Status: C Work Order Shop: W05

COLOR:	COMPANY: 001	TIRE SIZE 1:	FUEL TYPE 1: U
YEAR: 2012	DEPT: Transport	TIRE SIZE 2:	FUEL T YPE 2:
MAKE: FORD	CLASS: 175	ENGINE SIZE:	FUEL TYPE 3:
MODEL: E-350	SITE: 175	TRANS:	EQ AVAIL CODE: 1
LICENSE: temp	SERIAL #: 1FDEE3FS0CDA67417	TITLE:	BILLING CODE: 1
OPERATOR:	MONITOR GROUP:	CURRENT METERS:	M 136,229

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
927	1.04	N	1	04/26/2016	2034LN1100BN	Light System Light Exterior Replace	46.88
SUBTOTAL:							46.88

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
46742	NS	1	2.67	04/26/2016	2034LN1100BN	Light System Light Exterior Replace	2.67
43850	NS	1	2.43	04/26/2016	2034LN1100BN	Light System Light Exterior Replace	2.43
66980	NS	1	4.91	04/26/2016	2034LN1100BN	Light System Light Exterior Replace	4.91
SUBTOTAL:							10.01

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
WO Charge	Flat Rate Work Order Charge	04/26/2016	2020A00604BS	Work Order Flat Rate Charge	5.63
SUBTOTAL:					5.63

WORK ORDER TOTALS

TOTAL: 62.52

NOTES

9606-

1. Truck came in. Missing red clearance light on right rear. Light holder is broken. Ordered new light and holder

1 each grote red clearance light and holder ATTN KIM

Replaced the light.
Mark.

FASTER WORK ORDER PRINT

WORK ORDER # 71901 EQUIPMENT # 9606

Date In: 05/10/2016 Date Out: 05/10/2016 Work Order Status: C Work Order Shop: W05

COLOR:	COMPANY: 001	TIRE SIZE 1:	FUEL TYPE 1: U
YEAR: 2012	DEPT: Transport	TIRE SIZE 2:	FUEL T YPE 2:
MAKE: FORD	CLASS: 175	ENGINE SIZE:	FUEL TYPE 3:
MODEL: E-350	SITE: 175	TRANS:	EQ AVAIL CODE: 1
LICENSE: temp	SERIAL #: 1FDEE3FS0CDA67417	TITLE:	BILLING CODE: 1
OPERATOR:	MONITOR GROUP:	CURRENT METERS:	M 138,083

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
957	1.87	N	1	05/10/2016	PMA BS	A Service List	45.00
957	0.40	N	1	05/10/2016	1034LN2100BS	Light System Light Interior Replace	17.83
SUBTOTAL:							62.83

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
f1820s	NS	1	3.61	05/10/2016	PMA BS	A Service List	3.61
fa1632	NS	1	11.83	05/10/2016	PMA BS	A Service List	11.83
5w30	S	7	1.86	05/10/2016	PMA BS	A Service List	13.02
ri32478	NS	1	33.34	05/10/2016	1034LN2100BS	Light System Light Interior Replace	33.34
SUBTOTAL:							61.80

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
WO Charge	Flat Rate Work Order Charge	05/10/2016	2020A00604BS	Work Order Flat Rate Charge	7.54
SUBTOTAL:					7.54

WORK ORDER TOTALS	TOTAL:	132.17
-------------------	--------	--------

NOTES

FASTER WORK ORDER PRINT

**WORK ORDER # 71901
EQUIPMENT # 9606**

9606- Shep

1. PMA
2. Found wheelchair lift missing for lens cover on light. Light that is by the yellow arm. Replaced light lens. I saw a hazard of someone on lift getting burned by light bulb.

CHANGE OIL AND FILTER (6.5QTS 6.8L V10)
LUBE SUSPENSION
CHECK ALL EXTERIOR LIGHTS
CHECK ALL INTERIOR LIGHTS
INSTALL GREASE ZERKS WHEN NEEDED

ITEMS CHECKED:

- EXHAUST SYSTEM
- TIRE PRESSURE AND TIRE CONDITION (ADD AIR IF NEEDED)
- ALL FLUID LEVELS (ADD IF NEEDED)
- SUSPENION AND STEERING PARTS
- BRAKES
- BELTS
- HOSES
- FOR LEAKS
- AIR FILTERS (REPLACE IF NEEDED)
- CHECK BATTERIES (REPLACE IF NEEDED)

6.8L V10 6.5qts 5w-30

1 each oil filter FL-820S
1 each air filter FA-1632

PLEASE ACTIVATE OIL

1 each light 32478 for wheel chair lift. Kansas truck mobility, Talked with alicia. Eldorado serial truck number is EFRA201MC05A1257

FASTER WORK ORDER PRINT

WORK ORDER # 72401 EQUIPMENT # 9606

Date In: 06/30/2016 Date Out: 06/30/2016 Work Order Status: C Work Order Shop: W05

COLOR:	COMPANY: 001	TIRE SIZE 1:	FUEL TYPE 1: U
YEAR: 2012	DEPT: Transport	TIRE SIZE 2:	FUEL T YPE 2:
MAKE: FORD	CLASS: 175	ENGINE SIZE:	FUEL TYPE 3:
MODEL: E-350	SITE: 175	TRANS:	EQ AVAIL CODE: 1
LICENSE: temp	SERIAL #: 1FDEE3FS0CDA67417	TITLE:	BILLING CODE: 1
OPERATOR:	MONITOR GROUP:	CURRENT METERS:	M 143,283

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
957	1.74	N	N	06/30/2016	PMA BS	A Service List	45.00
957	0.47	N	N	06/30/2016	1034LN2100BS	Light System Light Interior Replace	21.10
SUBTOTAL:							66.10

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
fl820s	NS	1	3.61	06/30/2016	PMA BS	A Service List	3.61
5w30	S	7	1.86	06/30/2016	PMA BS	A Service List	13.02
ri32478	NS	1	34.18	06/30/2016	1034LN2100BS	Light System Light Interior Replace	34.18
SUBTOTAL:							50.81

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
WO Charge	Flat Rate Work Order Charge	06/30/2016	2020A00604BS	Work Order Flat Rate Charge	7.93
SUBTOTAL:					7.93

WORK ORDER TOTALS	TOTAL:	124.84
-------------------	--------	--------

NOTES

FASTER WORK ORDER PRINT

WORK ORDER # 72401
EQUIPMENT # 9606

Shep, pma.

1. PMA
2. Left lift light missing lens again. Last time just replaced the lens. Replace the ENTIRE light this time.

CHANGE OIL AND FILTER (6.5QTS 6.8L V10)
LUBE SUSPENSION
CHECK ALL EXTERIOR LIGHTS
CHECK ALL INTERIOR LIGHTS
INSTALL GREASE ZERKS WHEN NEEDED
CHECK PATIENT AIR FILTER CLEAN IF NEEDED

ITEMS CHECKED:

- EXHAUST SYSTEM
- TIRE PRESSURE AND TIRE CONDITION (ADD AIR IF NEEDED)
- ALL FLUID LEVELS (ADD IF NEEDED)
- SUSPENION AND STEERING PARTS
- BRAKES
- BELTS
- HOSES
- FOR LEAKS
- AIR FILTERS (REPLACE IF NEEDED)
- CHECK BATTERIES (REPLACE IF NEEDED)

6.8L V10 6.5qts 5w-30

1 each oil filter FL-820S

PLEASE ACTIVATE OIL

1 each light 32478 for wheel chair lift. Kansas truck mobility, Eldorado serial truck number is EFRA20IMC05A1257



BLUE BIRD



www.kansastruck.net



Tel: (316) 722-4291 • Toll Free: (800) 365-0217 • Fax: (316) 722-5917

R/O 08630		VIN 1 F D E E 3 F S 0 C D A 6 7 4 1 7		SEDGWICK CO DEPT ON AGING		DATE IN 07/15/16	
YEAR 2012	MAKE FORD	MODEL E350 SUPER	COLOR O	2612 W Central Ste 500		TIME IN 13:20	
MILES IN 144901	MILES OUT 144901	FIRST USE 00/00/00	LISC. KS	WICHITA KS 67213		CLOSED 13:25	
SEE ALSO				RES. BUS.		07/15/16	
				H: (316) 660-5150 W: (316) -		WRITER RYAN\04	

(1) LIFT IS LEAKING FLUID
HYDRAULIC CYLINDER CAME APART
REBUILT HYDRAULIC CYLINDER
REPLACED MISSING STOW LOCK BLOCK
STRAIGHTENED OUTER BARRIER FOOT
LUBED LIFT
(Tech:29) A

Labor	T29	88.00
RI-21829	(SEAL KIT) 1	91.97
RI-V2-AC-103	(CATCH PLASTIC) 1	11.26
Total Labor		88.00
Total Parts		103.23
Total Repair (Customer)		191.23

Vendor # 359

Doc # _____

Authorizer: DS/BA

340359-16 FC254 GL45104
SC 90837

9606

		W/C	INT.	CUSTOMER
DISCLAIMER OF WARRANTIES				
Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability, of fitness for a particular purpose, and the seller assumes no liability for any person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.		.00	.00	Labor 88.00
X _____				Parts 103.23
CUSTOMER SIGNATURE				Sublet .00
Page 1 of 1				Shop Supplie 5.28
Job 08630				Oil/Grease .00
08630		.00	.00	Sub Total 196.51
Customer Copy				Tax .00
				Total (Chrg) 196.51

FASTER WORK ORDER PRINT

WORK ORDER # 72541
EQUIPMENT # 9606

Date In: 07/13/2016 Date Out: 07/13/2016 Work Order Status: C Work Order Shop: W05

COLOR:	COMPANY: 001	TIRE SIZE 1:	FUEL TYPE 1: U
YEAR: 2012	DEPT: Transport	TIRE SIZE 2:	FUEL TYPE 2:
MAKE: FORD	CLASS: 175	ENGINE SIZE:	FUEL TYPE 3:
MODEL: E-350	SITE: 175	TRANS:	EQ AVAIL CODE: 1
LICENSE: temp	SERIAL #: 1FDEE3FS0CDA67417	TITLE:	BILLING CODE: 1
OPERATOR:	MONITOR GROUP:	CURRENT METERS:	M 144,597

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
957	1.38	N	N	07/13/2016	2032SR4100BN	Cranking System Starter Light Replace	62.18
SUBTOTAL:							62.18

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
sa988	NS	1	248.79	07/13/2016	2032SR4100BN	Cranking System Starter Light Replace	248.79
SUBTOTAL:							248.79

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
WO Charge	Flat Rate Work Order Charge	07/13/2016	2020A00604BS	Work Order Flat Rate Charge	7.46
SUBTOTAL:					7.46

WORK ORDER TOTALS	TOTAL:	318.43
-------------------	--------	--------

NOTES

Shep, starter is bad. Gear is touching flywheel. Replace with motorcraft.

1 each starter motorcraft

FASTER WORK ORDER PRINT

WORK ORDER # 72934
EQUIPMENT # 9606

Date In: 08/17/2016 Date Out: 08/17/2016 Work Order Status: C Work Order Shop: W05

COLOR:	COMPANY: 001	TIRE SIZE 1:	FUEL TYPE 1: U
YEAR: 2012	DEPT: Transport	TIRE SIZE 2:	FUEL TYPE 2:
MAKE: FORD	CLASS: 175	ENGINE SIZE:	FUEL TYPE 3:
MODEL: E-350	SITE: 175	TRANS:	EQ AVAIL CODE: 1
LICENSE: temp	SERIAL #: 1FDEE3FS0CDA67417	TITLE:	BILLING CODE: 1
OPERATOR:	MONITOR GROUP:	CURRENT METERS:	M 148,667

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
957	0.93	N	N	08/17/2016	PMA BS	A Service List	45.00
957	0.76	N	N	08/17/2016	1017TM3001BS	Tire / Tube Tire Light Diagnosis	34.17
957	0.26	N	N	08/17/2016	1017TM3165BS	Tire / Tube Tire Light Repair	11.50
957	0.20	N	N	08/17/2016	1017TM3110BS	Tire / Tube Tire Light Replace Front	8.86
957	1.34	N	N	08/17/2016	1017TM3110BS	Tire / Tube Tire Light Replace Front	60.44
957	0.02	N	N	08/17/2016	PMA BS	A Service List	0.00
SUBTOTAL:							159.97

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
f1820s	NS	1	3.61	08/17/2016	PMA BS	A Service List	3.61
fa1632	NS	1	11.83	08/17/2016	PMA BS	A Service List	11.83
8404	NS	2	252.13	08/17/2016	1017TM3110BS	Tire / Tube Tire Light Replace Front	504.26
5w30	S	7	1.86	08/17/2016	PMA BS	A Service List	13.02
SUBTOTAL:							532.72

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
WO Charge	Flat Rate Work Order Charge	08/17/2016	2020A00604BS	Work Order Flat Rate Charge	19.20
SUBTOTAL:					19.20

WORK ORDER TOTALS	TOTAL:	711.89
-------------------	--------	--------

NOTES

FASTER WORK ORDER PRINT

**WORK ORDER # 72934
EQUIPMENT # 9606**

Shep, pma.

1. PMA
2. Front tires worn. Replace tires.
3. LRI flat. Found valve stem leaking. Replaced valve core. No leaks.

CHANGE OIL AND FILTER (6.5QTS 6.8L V10)
LUBE SUSPENSION
CHECK ALL EXTERIOR LIGHTS
CHECK ALL INTERIOR LIGHTS
INSTALL GREASE ZERKS WHEN NEEDED
CHECK PATIENT AIR FILTER CLEAN IF NEEDED

ITEMS CHECKED:

- EXHAUST SYSTEM
- TIRE PRESSURE AND TIRE CONDITION (ADD AIR IF NEEDED)
- ALL FLUID LEVELS (ADD IF NEEDED)
- SUSPENION AND STEERING PARTS
- BRAKES
- BELTS
- HOSES
- FOR LEAKS
- AIR FILTERS (REPLACE IF NEEDED)
- CHECK BATTERIES (REPLACE IF NEEDED)

6.8L V10 6.5qts 5w-30

1 each oil filter FL-820S
1 each air filter FA-1632

PLEASE ACTIVATE OIL

2 each ambulance tires