

FASTER WORK ORDER PRINT

DATE: 11/04/2015 09:49

WORK ORDER # 69870
EQUIPMENT # 9605

Date In: 10/01/2015 Date Out: 10/02/2015 Work Order Status: C Work Order Shop: W05

COLOR:	COMPANY: 001	TIRE SIZE 1:	FUEL TYPE 1: U
YEAR: 2011	DEPT: Trans/Agin	TIRE SIZE 2:	FUEL T YPE 2:
MAKE: DODGE	CLASS: 164	ENGINE SIZE:	FUEL TYPE 3:
MODEL: GRAND	SITE: 164	TRANS:	EQ AVAIL CODE: 1
LICENSE: 78066	SERIAL #: 2D4RN4DG4BR628761	TITLE: *	BILLING CODE: 1
OPERATOR:	MONITOR GROUP:	CURRENT METERS:	M 106,284

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
957	0.36	N	1	10/02/2015	PMA BS	A Service List	45.00
957	0.43	N	1	10/02/2015	PMA BS	A Service List	0.00
957	0.87	N	1	10/02/2015	1013DJ1110BS	Brake Group Disc Pad Brake Replace Front	39.35
957	1.34	N	1	10/02/2015	1017TM3110BS	Tire / Tube Tire Light Replace Front	60.21
957	0.20	N	1	10/02/2015	PMA BS	A Service List	0.00
SUBTOTAL:							144.56

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
g7526	NS	1	4.18	10/02/2015	PMA BS	A Service List	4.18
p9737	NS	1	8.68	10/02/2015	PMA BS	A Service List	8.68
1842606a	NS	2	61.01	10/02/2015	1013DJ1110BS	Brake Group Disc Pad Brake Replace	122.02
14d1273ach	NS	1	63.09	10/02/2015	1013DJ1110BS	Brake Group Disc Pad Brake Replace	63.09
65324	NS	1	4.12	10/02/2015	PMA BS	A Service List	4.12
132337	NS	2	157.29	10/02/2015	1017TM3110BS	Tire / Tube Tire Light Replace Front	314.58
5w20	S	6	1.86	10/02/2015	PMA BS	A Service List	11.16
SUBTOTAL:							527.83

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
WO Charge	Flat Rate Work Order Charge	10/02/2015	2020A00604BS	Work Order Flat Rate Charge	17.35
SUBTOTAL:					17.35

WORK ORDER TOTALS	TOTAL:	689.74
-------------------	--------	--------

NOTES

FASTER WORK ORDER PRINT

WORK ORDER # 69870
EQUIPMENT # 9605

Shep, pma, Replace front brakes.

- 1.PMA
- 2.Front brakes
- 3.Front tires
- 4.Found driver rear air bag with a slit. Not leaking was advised to let it go.

CHANGE OIL AND FILTER (6.5QTS 6.8L V10) (16.QTS 6.0L) (14.6 QTS 6.6L)
LUBE SUSPENSION
CHECK ALL EXTERIOR LIGHTS
CHECK ALL INTERIOR LIGHTS
INSTALL GREASE ZERKS WHEN NEEDED
CHECK PATIENT AIR FILTER CLEAN IF NEEDED

ITEMS CHECKED:

- EXHAUST SYSTEM
- TIRE PRESSURE AND TIRE CONDITION (ADD AIR IF NEEDED)
- ALL FLUID LEVELS (ADD IF NEEDED)
- SUSPENION AND STEERING PARTS
- BRAKES
- BELTS
- HOSES
- FOR LEAKS
- AIR FILTERS (REPLACE IF NEEDED)
- CHECK BATTERIES (REPLACE IF NEEDED)

1 each Oil filter 67144
1 each air filter P9737
1 each engine oil pan drain plug

1 each front brake pads DELCO is ok
2 each front brake rotors DELCO is ok

2 each 225/65R16

PLEASE ACTIVATE OIL

FASTER WORK ORDER PRINT

WORK ORDER # 70625 EQUIPMENT # 9605

Date In: 12/24/2015 Date Out: 12/28/2015 Work Order Status: C Work Order Shop: W05

COLOR:	COMPANY: 001	TIRE SIZE 1:	FUEL TYPE 1: U
YEAR: 2011	DEPT: Trans/AgIn	TIRE SIZE 2:	FUEL T YPE 2:
MAKE: DODGE	CLASS: 164	ENGINE SIZE:	FUEL TYPE 3:
MODEL: GRAND	SITE: 164	TRANS:	EQ AVAIL CODE: 1
LICENSE: 78066	SERIAL #: 2D4RN4DG4BR628761	TITLE:	BILLING CODE: 1
OPERATOR:	MONITOR GROUP:	CURRENT METERS:	M 113,163

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	OPID	DATE	BACK	REPAIR	TYPE	RTY	DESCRIPTION	SUBLET COST
AMERICAN AUTO GLASS - charge	199.98	40.00	0.00	ch	12/28/2015	3007WN0100BS	Glass-Component	Windshield Repl			239.98

SUBTOTAL: 239.98

WORK ORDER TOTALS

TOTAL: 239.98

NOTES

replace windshield

Invoice



KANSAS FIRE EQUIPMENT CO., INC
123 S. OSAGE
WICHITA, KS 67213
www.kansasfire.com
(316) 262-8943

Invoice Number: 0423852-IN

Invoice Date: 2/19/2016

Service #: 0011

Account No: 0045480

Bill To:

DEPT ON AGING & TRANSPORT.
2622 W. CENTRAL #500
ATTN: KANDACE BONNESEN
WICHITA, KS 67203

Address Serviced:

SEDG. CO. DEPT. ON AGING & TR
2622 W. CENTRAL #500
ATTN: KANDACE BONNESEN
WICHITA, KS 67203

Customer P.O.		Confirm To:	Terms		
			NET 30 DAYS		
		A150241			
Quantity	Item	Description	Price	Amount	
1	/B417T	AMEREX 2.5 ABC FIRE EXT. W/VBK	38.50	38.50	

Vendor # 200

Doc # _____

Authorizer RS/BA

340359-16 FC254 6L42411

Please pay from this invoice.
Return 1 copy of invoice with payment.

LATE CHARGE: 2% FOR EACH ADDITIONAL MONTH AFTER 30 DAYS

Net Invoice: 38.50

Freight: 0.00

Sales Tax: 0.00

Invoice Total: 38.50

FASTER WORK ORDER PRINT

**WORK ORDER # 71999
EQUIPMENT # 9605**

Date In: 05/20/2016 Date Out: 05/20/2016 Work Order Status: C Work Order Shop: W05

COLOR:	COMPANY: 001	TIRE SIZE 1:	FUEL TYPE 1: U
YEAR: 2011	DEPT: Trans/Agin	TIRE SIZE 2:	FUEL TYPE 2:
MAKE: DODGE	CLASS: 164	ENGINE SIZE:	FUEL TYPE 3:
MODEL: GRAND	SITE: 164	TRANS:	EQ AVAIL CODE: 1
LICENSE: 78066	SERIAL #: 2D4RN4DG4BR628761	TITLE:	BILLING CODE: 1
OPERATOR:	MONITOR GROUP:	CURRENT METERS:	M 116,856

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
936	1.14	N	N	05/20/2016	PMA BS	A Service List	45.00
936	1.09	N	N	05/20/2016	1013DJ1115BS	Brake Group Disc Pad Brake Replace Rear	49.15
SUBTOTAL:							94.15

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
YH245038	NS	1	55.15	05/20/2016	1013DJ1115BS	Brake Group Disc Pad Brake Replace Rear	55.15
p9737	NS	1	8.68	05/20/2016	PMA BS	A Service List	8.68
g7526	NS	1	5.48	05/20/2016	PMA BS	A Service List	5.48
YH245038	NS	1	55.15	05/20/2016	PMA BS	A Service List	55.15
pxd1326h	NS	1	48.78	05/20/2016	1013DJ1115BS	Brake Group Disc Pad Brake Replace Rear	48.78
YH245038	NS	1	55.15	05/20/2016	1013DJ1115BS	Brake Group Disc Pad Brake Replace Rear	55.15
YH245038	NS	1	-55.15	05/20/2016	PMA BS	A Service List	-55.15
SUBTOTAL:							173.24

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
WO Charge	Flat Rate Work Order Charge	05/20/2016	2020A00604BS	Work Order Flat Rate Charge	11.30
SUBTOTAL:					11.30

WORK ORDER TOTALS

TOTAL: 278.69

NOTES

FASTER WORK ORDER PRINT

WORK ORDER # 71999
EQUIPMENT # 9605

Phil, pma.
PMA

CURRENT IDLE HOURS

INSTALL MILEAGE DECAL DONE

RE-SET OIL LIFE DONE

CHANGE OIL AND FILTER
LUBE SUSPENSION
INSTALL GREASE ZERKS WHEN NEEDED

ITEMS CHECKED:

- EXHAUST SYSTEM
- TIRE PRESSURE AND TIRE CONDITION (ADD AIR IF NEEDED)
- LF TREAD DEPTH 9/32
- RF TREAD DEPTH 9/32
- LR TREAD DEPTH 9/32
- RR TREAD DEPTH 9/32
- ALL FLUID LEVELS (ADD IF NEEDED)
- SUSPENSION AND STEERING PARTS
- FRONT BRAKES ESTIMATE REMAINING 35%
- REAR BRAKES ESTIMATE REMAINING 10%
- BELTS
- HOSES
- LEAKS
- AIR FILTER (REPLACE IF NEEDED)
- CHECK BATTERY
-

1 each oil filter

6 Quarts of oil 5-20

1 each Air Filter

=====

The front brakes will need replace on next service

RR rotor measurement .445

LR rotor measurement .460

Min. Spec. .409 due to grooves and pits I am replacing them

=====

1 each rear brake pad set
2 each rear rotors



BLUE BIRD



www.kansastruck.net



Tel: (316) 722-4291 • Toll Free: (800) 365-0217 • Fax: (316) 722-5917

R/O 08636		VIN 2 D 4 R N 4 D G 4 B R 6 2 8 7 6 1		SEDGWICK COUNTY DOA		DATE IN 07/18/16	
YEAR 2011	MAKE DODGE	MODEL GRAND CARA	COLOR O	2622 W. CENTRAL, STE 500		TIME IN 08:48	
MILES IN 121864	MILES OUT 121864	FIRST USE 00/00/00 00/00/00	LISC. KS	WICHITA KS 67203		CLOSED 08:53 07/18/16	
SEE ALSO				RES. H: (316) 660-5157	BUS. W: () -	WRITER KATHY\08	

(1) ELDORADO 16V-222 RECALL
CRIMPED ALL FUEL LINE CLAMPS
(Tech:29) A

Labor T29 2
..... (Warranty)

FOR Your RECORDS
9605

		W/C	INT.	CUSTOMER
DISCLAIMER OF WARRANTIES Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability of fitness for a particular purpose, and neither assumes nor authorizes any person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.				Labor .00
				Parts .00
				Sublet .00
		.00	.00	Shop Supplie .00
				Oil/Grease .00
				Sub Total .00
		.00	.00	Tax .00
X CUSTOMER SIGNATURE				Total .00
Page 1 of 1 Job 08636				
08636 Customer Copy				

FASTER WORK ORDER PRINT

WORK ORDER # 72522 EQUIPMENT # 9605

Date In: 07/12/2016 Date Out: 07/13/2016 Work Order Status: C Work Order Shop: W05

COLOR:	COMPANY: 001	TIRE SIZE 1:	FUEL TYPE 1: U
YEAR: 2011	DEPT: Trans/Agin	TIRE SIZE 2:	FUEL TYPE 2:
MAKE: DODGE	CLASS: 164	ENGINE SIZE:	FUEL TYPE 3:
MODEL: GRAND	SITE: 164	TRANS:	EQ AVAIL CODE: 1
LICENSE: 78066	SERIAL #: 2D4RN4DG4BR628761	TITLE:	BILLING CODE: 1
OPERATOR:	MONITOR GROUP:	CURRENT METERS:	M 121,420

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
936	0.94	N	N	07/12/2016	PMA BS	A Service List	45.00
936	0.02	N	N	07/12/2016	PMA BS	A Service List	0.00
936	0.93	N	N	07/12/2016	2017TM3110BN	Tire / Tube Tire Light Replace Front	41.95
936	0.98	N	N	07/12/2016	2013DJ1110BN	Brake Group Disc Pad Brake Replace Front	44.00
936	0.43	N	N	07/13/2016	2013DJ1110BN	Brake Group Disc Pad Brake Replace Front	19.48
SUBTOTAL:							150.43

PARTS ISSUED

PART NUMBER/DESCRIPTION	S/NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
qc1327	NS	1	66.71	07/12/2016	2013DJ1110BN	Brake Group Disc Pad Brake Replace Front	66.71
148011	NS	2	81.76	07/12/2016	2017TM3110BN	Tire / Tube Tire Light Replace Front	163.52
g7526	NS	1	5.48	07/12/2016	PMA BS	A Service List	5.48
5w30	S	5	1.86	07/12/2016	PMA BS	A Service List	9.30
5w30	S	6	1.86	07/13/2016	PMA BS	A Service List	11.16
5w30	S	5	-1.86	07/12/2016	PMA BS	A Service List	-9.30
SUBTOTAL:							246.87

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
WO Charge	Flat Rate Work Order Charge	07/13/2016	2020A00604BS	Work Order Flat Rate Charge	18.05
SUBTOTAL:					18.05

WORK ORDER TOTALS	TOTAL:	415.35
-------------------	--------	--------

NOTES

FASTER WORK ORDER PRINT

DATE: 08/11/2016 11:11

WORK ORDER # 72522
EQUIPMENT # 9605

Phil, pma. Right front tire picked up tar somewhere and now the steering wheel shakes. Replace right front tire or clean off tar so it doesnt vibrate. Create appropriate repair type.

PMA

CURRENT IDLE HOURS N/A

INSTALL MILEAGE DECAL DONE

RE-SET OIL LIFE DONE

CHANGE OIL AND FILTER

LUBE SUSPENSION

INSTALL GREASE ZERKS WHEN NEEDED

ITEMS CHECKED:

- EXHAUST SYSTEM
- TIRE PRESSURE AND TIRE CONDITION (ADD AIR IF NEEDED)
- LF TREAD DEPTH
- RF TREAD DEPTH
- LR TREAD DEPTH
- RR TREAD DEPTH
- ALL FLUID LEVELS (ADD IF NEEDED)
- SUSPENION AND STEERING PARTS
- FRONT BRAKES ESTIMATE REMAINING
- REAR BRAKES ESTIMATE REMAINING
- BELTS
- HOSES
- LEAKS
- AIR FILTER (REPLACE IF NEEDED)
- CHECK BATTERY
-

1 each oil filter

Quarts of oil 5-20

=====

1 each 225/65-16 BRIGESTONE DUELER HL tire

=====

1 each fornt brake pad set

Rotor spec. 26.4

Left 27.8

Right 27.7

FASTER WORK ORDER PRINT

WORK ORDER # 72597 EQUIPMENT # 9605

Date In: 07/19/2016 Date Out: None Work Order Status: Z Work Order Shop: W05

COLOR:	COMPANY: 001	TIRE SIZE 1:	FUEL TYPE 1: U
YEAR: 2011	DEPT: Trans/Agin	TIRE SIZE 2:	FUEL TYPE 2:
MAKE: DODGE	CLASS: 164	ENGINE SIZE:	FUEL TYPE 3:
MODEL: GRAND	SITE: 164	TRANS:	EQ AVAIL CODE: 1
LICENSE: 78066	SERIAL #: 2D4RN4DG4BR628761	TITLE:	BILLING CODE: 1
OPERATOR:	MONITOR GROUP:	CURRENT METERS:	M 121,936

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
936	1.60	N	N	07/20/2016	2016A00100BN	Suspension Air Ride Height Replace	72.01
936	2.61	N	N	07/21/2016	2016A00100BN	Suspension Air Ride Height Replace	117.53
963	0.05	N	N	07/19/2016	PMA BS	A Service List	45.00
963	1.57	N	N	07/19/2016	2016A00001BN	Suspension Air Ride Height Diagnosis	70.53
963	0.00	N	N	07/19/2016	2016A00001BN	Suspension Air Ride Height Diagnosis	0.08
SUBTOTAL:							305.15

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
35051	NS	1	652.06	07/20/2016	2016A00100BN	Suspension Air Ride Height Replace	652.06
35051	NS	1	652.06	07/20/2016	2016A00100BN	Suspension Air Ride Height Replace	652.06
73010	NS	1	466.23	07/29/2016	2016A00100BN	Suspension Air Ride Height Replace	466.23
SUBTOTAL:							1,770.35

WORK ORDER TOTALS	TOTAL:	2,075.50
-------------------	--------	----------

NOTES

Beau, rear air suspension leaks down. Inspect system and find the leaks.

Leak checked by filling the system and spraying all components down with soap water. Found right rear air bag leaking and left rear is cracked about to start leaking.

Parts:

2 Rear suspension air bag assemblies. This is a transportation van.
07/19/2016 @ 08:24:10

1 ea. air ride control valve

Spoke with John @ Jay Hatfield Mobility....will call back once part is located....Chris

Air lines has been re-routed until new valve comes in

Ordered valve from Kevin @ Jay Hatfield mobility and it should be in Tuesday 7/26 or Wednesday 7/27....Chris

Valve was received on 7/28 and was placed on Phil's desk....Chris